



Order Desk: 1-800-651-7445

Fax: 1-905-335-1829

E-Mail: info@fmsiinc.com

<http://www.fmsiinc.com>

WHY FUEL LINES FAIL



- Exposure to the environment causes fuel lines to rust out
- Rusted and seized tube fittings will cause fuel lines to collapse/kink during replacment of fuel filter, fuel tank and fuel pump assembly.
- Punctured fuel lines and flex hoses caused by road debris.
- Leakage due to aged and brittle flex hose and crimps.

WHY NOT SIMPLY REPAIR

- The Fuel line is an intricate part of the fuel delivery system between the fuel tank and the engine requiring a very precise fix. This precise fit is not obtainable from repair job.
- Improper line or hose sizing during repairs will cause poor vehicle performance from fuel flow restrictions
- High internal psi from the fuel pump causes defective fuel lines to leak, creating a serious safety issue.

WHY USE OUR FUEL LINES

- Quick, easy installation
- Designed, manufactured and tested to fit O.E. fit form and Function
- Fixed right the first time



Part #	Description	Jobber
FL 146-A	Chev 97'-00' 2wd ref Cab 8'ft Box	\$161.73
FL 400-A	Chev 90'-95' 2wd Reg Cab 8'ft Box	\$136.07
FL 400-B	Chev 88'-95' 2dr Reg Cab 6.5'ft Box	\$136.07
FL400-C	Chev 88'-95' 2dr Ext Cab 8'ft Box	\$136.07
FL 400-E	Chev 88'-89' 2wd Reg Cab 8'ft Box	\$136.07
FL 400-F	Chev 96'-97' 2wd Reg Cab 8'ft Box	\$136.07
FL 400-R	Chev 88'-89' 4wd Reg Cab 8'ft Box	\$136.07

Part #	Description	Jobber
FL 400-S	Chev 90'-95' 4wd Reg Cab 8'ft Box	\$136.07
FL 400-T	Chev 96'-97' 4wd Reg Cab 8'ft Box	\$136.07
FL 400-U	Chev 88'-89' 4wd Ext Cab 6'ft Box	\$136.07
FL 400-V	Chev 90'-95' 4wd Ext Cab 6'ft Box	\$136.07
FL 400-X	Chev 88'-89' 4wd Ext Cab 8'ft Box	\$136.07
FL 441-B	92'-94' S Series - Blazer, Jimmy, 4dr 2 & 4wd	\$161.73
FL 443-A	95' S Series - Blazer, Jimmy, 4dr 2 & 4wd	\$161.73

For more information on FMSI Automotive Hardware Products Contact: 1-800-651-7445 or Email us at info@fmsiinc.com